










1		<p>Max 60 sec.</p>		
----------	--	--------------------	--	--




2		...		Install driver
----------	--	-----	--	----------------

3				
----------	--	--	--	--

4	<p>Windows XP:</p>			Shut down
	<p>Windows 2000, ME, 98se:</p>			

5	 <p>A hand is shown plugging a cable into a power outlet. A red arrow points to the plug. A black arrow points to the right, leading to a photo of a hand opening a computer case. A red lightning bolt symbol with a slash is on the right.</p>	
6	 <p>Internal view of the bay with cables labeled: BLACK, YELLOW, RED, BLUE, and POWER. A red arrow points to the power cable.</p>	Connect
7	 <p>Photo of the bay being inserted into a computer case. Red arrows point to the bay and the case.</p>	Place BAY
8	 <p>Close-up photo of the bay being mounted into a slot. White circles highlight the mounting points.</p>	Mount BAY

9		Place / mount bracket
10		Connect power cable
11		
12		Connect back site

<p>13</p>		 <p>Power on</p>
<p>14</p>		<p>Ok!</p>
<p>15</p>	<p>Finish</p>	

